

# Contents

<b>1</b>	<b>Introduction</b> .....	9
<b>2</b>	<b>Objective</b> .....	9
<b>3</b>	<b>Scope</b> .....	9
<b>4</b>	<b>Key Definitions and Responsibilities</b> .....	10
4.1	Key Definitions .....	10
4.2	Responsibilities .....	10
<b>5</b>	<b>Key Regulatory Requirements</b> .....	10
<b>6</b>	<b>Criticality Assessment</b> .....	11
6.1	Criticality Assessment Team (CAT) .....	11
6.1.1	Team Meetings .....	12
6.2	Categorization .....	12
6.3	Ranges and Limits .....	12
6.4	Rationale .....	12
6.5	Periodicity .....	13
6.6	Process Change .....	13
<b>7</b>	<b>Life Cycle Phases</b> .....	13
7.1	Project Phase .....	13
7.2	Pre-Operational Calibration Phase .....	14
7.3	Operational Phase .....	14
7.4	Key Requirements for Life Cycle Phases .....	14
<b>8</b>	<b>Project Phase</b> .....	14
8.1	Responsibilities .....	14
8.1.1	Process .....	14
8.1.2	Engineering .....	15
8.1.3	Quality .....	15
8.2	Specification of the Instrument .....	15
8.2.1	Range .....	15
8.2.2	Accuracy .....	15
8.2.3	Hysteresis/Temperature Affects/Non-Linearity .....	16
8.2.4	Uncertainties .....	16
8.3	Labeling .....	16
8.4	Calibration Process .....	16
8.4.1	Instrument Testing .....	16
8.4.2	Instrument Loop Testing .....	16
8.5	Installation Qualification Sign Off .....	17
<b>9</b>	<b>Pre-Operational Phase</b> .....	17
<b>10</b>	<b>Operational Phase</b> .....	17
10.1	Responsibilities .....	17
10.1.1	Instrument Calibrator .....	17
10.2	Cleaning and Decontamination .....	17
10.3	Calibration Process .....	18
10.3.1	Instrument Calibration .....	18
10.3.2	Loop Calibration .....	18
10.3.3	Non-Conformance .....	18
10.3.4	Third Party Calibration .....	18
10.4	Documentation: Calibration Records .....	19
10.4.1	Calibration Request Documents .....	20
10.4.2	Certificate of Calibration .....	20
10.4.3	Non-Conformance Documentation .....	20
10.5	Removal: Decommissioning of the Instrument .....	21

<b>11</b>	<b>Training</b> .....	21
11.1	Training Records .....	21
<b>12</b>	<b>Change Control</b> .....	22
<b>13</b>	<b>Documentation</b> .....	23
<b>14</b>	<b>Electronic Records</b> .....	23
<b>15</b>	<b>Auditing</b> .....	24
15.1	Calibration Management Auditing .....	24
15.2	Third Party Auditing .....	24
<b>16</b>	<b>Other Considerations</b> .....	24
16.1	Automation and Smart Instrumentation .....	24
16.2	Automation .....	25
16.3	Diagnostic and Calibration Development Trends in Smart Instrumentation .....	25
16.3.1	Measurement Integrity Validation and Self Calibration .....	25
<b>17</b>	<b>Calibration Management Software</b> .....	25
<b>18</b>	<b>Smart Calibrators and Test Equipment</b> .....	26
<b>19</b>	<b>References</b> .....	26
<b>20</b>	<b>Glossary</b> .....	26
20.1	Acronyms .....	26
20.2	Definitions .....	27

A large, light gray watermark of the ISPE logo is centered on the page. The logo consists of the letters 'ISPE' in a bold, sans-serif font, with a registered trademark symbol (®) to the right. The letters are superimposed on a stylized globe with latitude and longitude lines.